



CALIBRATION
 Patch unconnected cable to InA-2.
 Adjust TRbal for symmetry and minimum CV leak-through.
 Adjust TRgain so that B input is not audible in xfade mode with Pofs at 100%
 Repeat until satisfaction.

Kymatica Devices

Sheet: /
 File: VCA_XF_RM.sch

Title: VCA/4QM/XFADE

Size: A4	Date: 2016-11-20	Rev: 0.97
KiCad E.D.A. kicad (2016-09-30 revision 278ee7d)-master		Id: 1/1